





## Onshore Onshore Decontamination

• Decontamination is achieved with chemical circulation in a HEFU or HEFT or utilising HPWJ



 HPWJ Ultra-high pressure decontamination using Automated High Pressure Decontamination Facility



Decontamination to non-detectable Levels

For Solutions
Scan Here

